

25X1A
25X1A
25X1A
25X1A

- A. RX6856
- B. FILM EVALUATION REPORT
- C. TYPE 1/C/3888
- D. FULTRON 202/MX578/47" SEC/87 DEGREES F./HAF 1.30- BAR 1.28
- E. 2.80/2.81
- F. 3404/2134/405-4-3-11-7
- G. (1) GOOD
- (2) NORMAL
- (3) MEDIUM
- (4) GOOD
- (5) OPERATIONAL
- (6) NORMAL
- (7) 95 PERCENT CLOUD COVER NORTH VIETNAM/68 PERCENT CLOUD COVER
OVERALL MISSION.
- H. O.N. DISPOSITION TO [REDACTED]
- 3 DUPE POS TO NATIONAL CUSTOMERS
- 6 DUPE POS 2 DUPE NEGS TO THEATER CUSTOMERS

25X1A

25X1A

PAGE 4 [REDACTED] 0173 T O P S E C R E T

1. NORMAL STARTUP AND SHUT DOWN WITH OVERLAP IN FIRST 16 FRAMES
1/8" TO 3/4" AITC FRAMES. 1/2 IN. OF FORWARD CLOCKS IN IMAGERY
EVERY OTHER FRAMES APPROX 1/8" INTO FRAME. BACK ABRASSIONS 2"
IN FROM TRAILING EDGE FROM 830 TO END OF MISSION. RECYCLING FROM
936 THROUGH 973. PRESSURE MARKS ON BASE SIDE. STREAKS WERE NOTED ON
BASE OF PART 647 3" INCHES IN FROM LEADING EDGE. MINUS DENSITY
STREAKS IN FORWARD FRAMES NOTICEABLE ONLY IN HORIZON ON FORWARD
FRAMES. PLUS DENSITY STREAKS WERE APPARENT IN HORIZON ON FORWARD
FRAMES RUNNING FROM LEADING TO TRAILING EDGE. FACTORY SPLICE IN
FRAME 1102. PINHOLE IN 841 1/2" IN 1 3/4" FROM TRILING SIDE. PART 12
HAD NUMEROUS HANDLING SCRATCHES THROUGHOUT. FRAME 842, 1266, 1267,
1291 HAD NUMEROUS HANDLING SCRATCHES. 1308-1309 2 SCRATCHES 3
INCHES IN 1/4" APART. FRAMES 721-726 WERE OVERLAPED. 731, 734
HAD 5 STREAKS RUNNING VERTICAL. FRAMES 1304-1310 WERE FOG.

T O P S E C R E T

BT

BEST COPY
Available

120
0Z000150

FTP5 14/090015Z ZFF4 ZPO [REDACTED]

BT

XXXXX

25X1A

25X1A

25X1A

TOP SECRET 090010Z MARCH 68 CIT [REDACTED]

25X1A

- A. 8X056
B. INS TAPE EVALUATION REPORT
C. INS010
D. 8/1230Z
E. 1. SATISFACTORY
2. SATISFACTORY
3. SATISFACTORY
4. SATISFACTORY
5. SATISFACTORY
6. SATISFACTORY
7. SATISFACTORY
8. SATISFACTORY
9. SATISFACTORY
10. SATISFACTORY

F. A LINE OF DATA WAS GARBLED BETWEEN ELAPSED TIME 7907 AND 7917.
TWO LINES OF DATA WERE DISPLACED TO THE LEFT BETWEEN ELAPSED
TIME 7917 AND 7931. ONE LINE OF DATA WAS DISPLACED TO THE LEFT

25X1A

PAGE [REDACTED] TOP SECRET

BETWEEN ELAPSED TIME 8015 AND 8024. THREE LINES OF DATA WERE
DISPLACED TO THE LEFT BETWEEN ELAPSED TIME 8052 AND 8071. TAPE
APPEARS SATISFACTORY. ERRORS CAN BE SALVAGED. TAPE EVALUATION
PERTAINS TO CAMERA OPERATION ONLY.

TOP SECRET

BT

DCM